

INSPECTION REPORT

Basic Details			
Inspection Date 2	29-12-2023	Inspector	Hassan
Location A	Abu Dhabi		

Equipment Details				
Category	Bus – MK476771	Make	Mitsubishi	
Model	Rosa	Year	10-2003	
Km's	Not verified	Serial No.	JL5B2E6K64 – PD00310	
Chassis No.				

4WD	Xenon Head Lights	Air Condition	
Draw Bar			

Cab			
Seats	OK – Need upholstery	Cab Doors	OK
Switches	OK	Windows	ОК
Gauges	Some Need Maintenance	Wipers	Old
Aircon / Heater	Not Working	Floor Mates	ОК
Ceiling	OK		

Engine		Serial No.	
Leaks	Miner Leaks	Sound	ОК
Oil Condition	Old	Blow By	Normal
Exhaust	OK	Belts	OK, some are old
Cooling System	Need Maintenance & Cleaning	Power	Normal

Exterior			
Chassis	OK	Cooler Grill	Normal
Sheet Metal	Some Parts Rusty	Bumpers	OK
Door Handles	OK – Some Need Change	Lights	OK – Some Bulb Need Change
Paintwork	Some Parts need repaint		

Power Train			
Axels	ОК	Universal Joints	ОК
Gearbox	ОК	Differentials	ОК
Gearbox type	Manual	Brake Drums/Disk	ОК



INSPECTION REPORT

History & Servic	е						
Service Book Entries	NO						
Mileage Reasonable	YES						
Safety Checks	OK						
Limited Function	nal Test						
Drive Forward	OK		Wheel Bearing	0	K		
Drive Reverse	OK		Suspensions	N	ormal		
Service Brake	ОК		Park Brake	N	ormal		
Steering	ОК						
Tires	RHS mm (%) rem.	LH	S mm (%)		Cuts	Recapped	
Axle 1	50%	509	%				
Axle 2	50%	509	%				
Γ							
Notes:							
	tion of the bus is average, but i ervicing, seats upholstery resto lts.						

Any Written Info About Last Service & Mileage?	No