

Inspection Report - 2016 Cummins C330D5

Serial No: 15801760 | 15,098 hours | Location: United Arab Emirates | SKU: 678

Key Features & Condition	
Safety Certification Label	N/A
Diesel fuel	Ok
Housing	Ok
On Wheels	N/A
Housing	
Sheet Metal	Ok
Frames	Ok, Minor dint
Guards / Screens	Ok
Doors	Ok
Paintwork	Ok
Engine	
Model	Cummins QSL9G5
Leaks	Ok
Oil Condition	Ok
Exhaust	Ok
Smoke	Normal
Injection	Electronic
Noises	Ok
Cooling System	Ok
Blow By	Normal
Belts	Ok
Fluid Levels	Ok
Generator	
Noises	Ok
Cables	N/A
Sockets	N/A
Damages	Ok
Switchboard	Ok
Gauges	Ok
Warning messages	1117 power lost with ignition, 1246 general Engine fault



Tank / Fuel System	
Fuel Hoses	Ok
Tank	Ok
Leaks	Ok
Gauge Tank	N/A
Others	
Safety Switches	Ok
Rated Power kVA	330KVA
Regenerative power, kW	47
Fuses	Ok
If on Wheels	N/A
Tire Condition	N/A
Draw Bar	N/A
Lights	N/A
Alt voltage	399 V

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed

