

# Inspection report – 2015 Caterpillar 966H

Serial No: A18G02318 | Location: Jeddah, Ukraine | SKU: 7335

## **Key Features & Condition**

Safety Certification Label N ABoom Hydraulic Check Valve N AAdjustable Boom System N/A **Automatic Lubrication System** N\A Arm Hydraulic Check Valve N\A Diesel Particulate Filter NAHydraulic Hammer Lines N/A Grapple And Shear Hydraulic Lines N/A Diesel Exhaust Fluid System Addblue N AStabilizer Blade Condition NAN/A Horn

### **Operator Cabin Details**

Seat And Arm Support Ok

Cab Doors & Covers Ok,lock need repair

Control Levers, Control Stick Ok,rpm controller is not functional

Windows And Mirrors Ok, no mirrors

Dashboard Screen, Gauges Ok

Warning Alarms Message Check engine

Washer, Wipers N\A

Air Conditioning & Heating System Not functional

Cab Floor Covering Ok

Cab Structure, Gard Ok, minor rusty

Electrical System need minor service

### **Engine & Performance**

Fuel Injection System Electronic

Engine Model Cummins sce661ejdara

Engine Cooling System Ok

#### **PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



# PLANT & EQUIPMENT AUCTIONS

Engine Oil Check Ok
Cooling System Ok

Coolant Ok,normal water

Exhaust System & Muffler Ok
Belts & Air/Oil Filters Ok

Smoke Check Normal Blow BY Normal

Leaks & Seals Ok

# **Exterior Condition & Visual Inspection**

Main Frame & Track Frame Ok,idler base is welded Protective Covers & Sheets 3 covers are missing

Engine Hood Ok
Side Access Doors Ok
Steps And Handrails Ok

Boom Condition Ok, welded

Bumpers & Catwalk Condition Ok

Arm Condition Ok, welded

Lights 2Lights works,3need bulbs

Battery Check Ok

Cabin Compartments Ok, messing some covers

Exterior Paint Condition Ok,repainted

#### **Hydraulic System**

Hydraulic Leaks Minor leaks from control side &swing motor

Boom Hydraulic Jack Ok
Hydraulic Pump & Valve Block Ok
Bucket Hydraulic Jack Ok
Arm Hydraulic Jack Ok

# **Performance Analysis**

Boom Pins Condition Ok
Excavator Self- Drift Test Ok

Arm Pins Condition Ok, minor loose

#### **PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



# PLANT & EQUIPMENT AUCTIONS

Hydraulic Pump Noise Check Ok

Bucket Pins Condition Ok, minor loose

Slewing Ring Bearing Movement Check Ok

Swing Drive And Brake Test Need repair

Drive Force Test Ok

#### **Attachments**

Attachments Model bucket

Size w960,h1260,d850

Status Ok,need minor welding

Coupler Status Ok
Second Attachments Model N\A
Size N\A
Status N\A

# **Undercarriage**

**Bushings** 0.6 0.7 Track Shoes Idlers 0.6 Shoe Width In Mm: 600mm Track Pitch In Mm: 80mm **Carrier Rollers** 0.6 Track Rollers 0.6 Track Links 0.6 **Sprocket Segments** 0.6

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.



Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com

