




Basic Details			
Inspection Date	06/05/2024	Inspector	Eng. Basel Alkilisli
Location	Dubai – Jebel Ali – Plant & Equipment		


Equipment Details			
Category	Truck Head	Make	Renault (France)
Model	T460	Year	2016
Hours		Serial No.	VF611A168GD011107
Chassis No.		Km's	523,258 KM

CE Labeling	•	Tachograph	•	Extended Fuel tank	<input type="checkbox"/>
Automatic Shift	•	Auto Lube	<input type="checkbox"/>	Retarder	•
Semi-Automatic	•	A/C	•	Rear Axle Lifter	<input type="checkbox"/>
Cruise Control	•	Navigation	<input type="checkbox"/>	Radio	•
Cabin Refrigerator	<input type="checkbox"/>	ABS	<input type="checkbox"/>	TRC	•

Truck Cab				<a href="#">Click Here to View</a>	
Driver Seat	Ok	Cab Doors	Ok		
Switches, Levers	Ok	Windows, Mirrors	Ok		
Gauges, Warn Lights	Ok	Wipers, Washers	Ok		
Aircon / Heater	Ok	Interior, Covers	Ok		
Passenger Seat	Ok	Radio	Ok		

Engine				<a href="#">Click Here to View</a>	
Leaks, Seals	Ok	Smoke, Fume	Normal		
Oil Condition	Ok	Blow By	Ok		
Exhaust/Muffler	Ok	Belts, Pulleys	Ok		
Cooling System	Ok	Coolant Condition	Ok		

Visual inspection exterior				<a href="#">Click Here to View</a>	
Chassis, Frames	Ok	Cooler Grill	Ok		
Sheet Metal, Covers	Ok, batteries cover is missing	Bumpers	Ok		
Steps, Grab Irons	Ok	Lights	Ok, some bulbs need change		
Paintwork	Ok				

Power Train				<a href="#">Click Here to View</a>	
Axels/Differentials	Ok	Transfer Gear	Ok		
Stabilizers, Beams	Ok	Universal Joints	Ok		
Rubber Sleeves	Ok	Transmission	Ok		
Brake Pads/Disks	Ok	Clutch	No		
Compressor	Ok				

## Truck Limited Functional Test

[Click Here to View](#)



Transmission Forward	Ok	Park Brake	Ok
Transmission Reverse	Ok	Electrics	Ok
Automatic Group Select	Ok	Retarder	Ok
Service Brake	Ok		

[Click Here to View](#)



Tires	RHS mm (%)	LHS mm (%)	Tire Size
Axle 1	40%	40%	315/70 R22.5
Axle 2 Inside	40%	40%	315/70 R22.5
Axle 2 Outside	40%	40%	315/70 R22.5
Axle 3 Inside	40%	40%	315/70 R22.5
Axle 3 Outside	40%	40%	315/70 R22.5

**Notes:**

The truck head is in good working condition, and all its major parts are intact and functioning as intended.

Cabin tilting check locking warning is on.

*No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.*